ASSEMBLY

START HERE

1

101395
Power Distribution Unit

(20) 3' Cables

6' Power Cord

Unbox components.

2

Plug one end of power cord
into back of PDU.

3

Plug other end of power cord into an outlet.

4

Plug one end of cable into an
open spot on the PDU.

5

Plug other end of the cable into the
back of a Sauce+ or Spin+ unit.

6

Turn the power switch on the back of the
PDU to the on position. This will turn on
all connected units. It may take several
seconds for the units to turn on.

SERVER.

IxD™ SERIES

POWER DISTRIBUTION UNIT (PDU)
101395

Up to 20 Sauce+™ or Spin+™ units
can be plugged into a single PDU.

A PDU can handle up to 6 Sauce+ or Spin+
units dispensing or spinning at one time.

If a fuse blows in the PDU,
follow these simple steps:

- Unplug the power cord from
  the back of the unit
- Remove the fuse cartridge and
  replace the blown fuse(s)
- Reinsert the cartridge and plug
  the power cord into the unit

SERVER