

88554 PUMP GASKET REVISION

Server Products strives to provide the foodservice industry with simple, high-quality serving solutions.

Currently, select stainless steel remote and pouched dispensers, as well as 2 oz pumps feature a blue gasket (p/n 88554) that must be installed with the flat side facing up in order to fit properly.

To eliminate the confusion, Server has revised this gasket to be bi-directional for easier installation and to create a more efficient seal between the pump valve body and cylinder.

The new gasket will be effective on all applicable pumps manufactured April 9, 2018 or later.

With any inquiries, contact Customer Service: spsales@server-products.com.

Old gasket – one side is flat,
while the other features a ridge



Current, revised gasket –
both sides feature a ridge

